



Test Report issued under the responsibility of:



TEST REPORT IEC 60335-2-40 Safety of household and similar electrical appliances Part 2-40: Particular requirements for electrical heat pumps, air conditioners and dehumidifiers	
Report Number.....	<i>15TR-K0229</i>
Date of issue	<i>2015-09-09</i>
Total number of pages	<i>166</i>
Applicant's name	<i>TOSHIBA CARRIER CORPORATION</i>
Address.....	<i>336 Tadehara, Fuji-shi, Shizuoka-ken, JAPAN</i>
Test specification:	
Standard	<i>IEC 60335-2-40:2013 (Fifth Edition) in conjunction with IEC 60335-1:2010 (Fifth Edition)</i>
Test procedure.....	<i>CB Scheme</i>
Non-standard test method.....	<i>N/A</i>
Test Report Form No.....	<i>IEC60335_2_40K</i>
Test Report Form(s) Originator....	<i>VDE</i>
Master TRF	<i>Dated 2014-06</i>
Copyright © 2014 Worldwide System for Conformity Testing and Certification of Electrotechnical Equipment and Components (IECEE), Geneva, Switzerland. All rights reserved.	
This publication may be reproduced in whole or in part for non-commercial purposes as long as the IECEE is acknowledged as copyright owner and source of the material. IECEE takes no responsibility for and will not assume liability for damages resulting from the reader's interpretation of the reproduced material due to its placement and context.	
If this Test Report Form is used by non-IECEE members, the IECEE/IEC logo and the reference to the CB Scheme procedure shall be removed.	
This report is not valid as a CB Test Report unless signed by an approved CB Testing Laboratory and appended to a CB Test Certificate issued by an NCB in accordance with IECEE 02.	
General disclaimer:	
The test results presented in this report relate only to the object tested. This report shall not be reproduced, except in full, without the written approval of the Issuing CB Testing Laboratory. The authenticity of this Test Report and its contents can be verified by contacting the NCB, responsible for this Test Report.	

Test item description	<i>Air Conditioner Outdoor Unit</i>
Trade Mark	<i>TOSHIBA</i>
Manufacturer.....	<i>Toshiba Carrier Air Conditioning (China) Co., Ltd. Building 1, No. 60, 21st Avenue, Baiyang Street, Hangzhou Economic and Technological Development Area, China</i>
Model/Type reference.....	<i>MCY-MHP0404HS8-E, MCY-MHP0504HS8-E, MCY-MHP0604HS8-E, MCY-MHP0404HS8J-E, MCY-MHP0504HS8J-E, MCY-MHP0604HS8J-E, MCY-MHP0404HS8-TR, MCY-MHP0504HS8-TR, MCY-MHP0604HS8-TR, MCY-MHP0404HS8J-TR, MCY-MHP0504HS8J-TR, MCY-MHP0604HS8J-TR, MCY-MHP0404HS8-A, MCY-MHP0504HS8-A, MCY-MHP0604HS8-A</i>
Ratings.....	<i>380-415V 3N~, 50Hz, 12.5A, 8.5kW, Class I</i>